

Berwick Concrete Repairs

November 2016

KEY WORKS – Concrete Repair

SCOPE OF WORKS –

A concrete bench was damaged and repaired by others, but the repair failed.

Central Remedial's solution was to break out the old repair, install new steel pins and repair the area using a non-shrink repair mortar.

WORKS UNDERTAKEN –

- Breakout of old repair
- Installation of new steel pins
- Application of repair mortar

SITE PHOTOS –



Old Repair



Breakout and steel install



Applying repair mortar



Finished repair