

## Toorak Road Waterproofing

November 2016

**KEY WORKS** – Waterproofing, PU Injection

### **SCOPE OF WORKS** –

Water was leaking through the core filled block wall due to insufficient waterproofing.

Central Remedial's solution was to inject the wall with a water reactive PU injection material.

A silane spray was also applied to the block wall to further aid the waterproofing detail.

### **WORKS UNDERTAKEN** –

- Injection of PU waterproofing
- Application of Silane Waterproofing Spray

### **SITE PHOTOS** –



Drilling holes for injection



Injecting PU



PU reacting with water



Completed Joints