

## Cheltenham Bund Repairs

June 2016

**KEY WORKS** – Concrete Repair, Epoxy floor coating

### **SCOPE OF WORKS** –

As part of a building handover, a bund wall had to be removed. As a result, parts of the concrete floor was damaged.

Central Remedial's solution was to prepare the concrete substrate, repair large imperfections and apply an epoxy floor coating to the affected area.


### **WORKS UNDERTAKEN** –

- Preparation of substrate
- Repair of spalled areas
- Application epoxy floor coating


### **SITE PHOTOS** –



Preparing Substrate



Prepared floor



Applying epoxy floor coating



Finishing off area