

## SHIPLEY STREET JOINTING & WATERPROOFING

OCTOBER 2016

**KEY WORKS** – Waterproofing, Joint Replacement

### **SCOPE OF WORKS** –

Water was leaking through the existing mastic/grouted joints causing water to enter the apartment below.

To rectify the issue, Central remedial removed the existing mastic and grout, taped and primed all joints and sealed the joints with a PU mastic.

After the joints were cured, a silane spray was applied to the entire area to further aid the waterproofing detail.

### **WORKS UNDERTAKEN** –

- Joint Removal & Replacement
- Application of Silane Waterproofing Spray
- 

### **SITE PHOTOS** –



Joint Removal



Joint Preparation



Applying Silane Spray



Completed Joints